

FIG. 1A

PO2290" 95646860




FIG. 1B




FIG. 2




Fig. 3






FIG. 4



Wicking

Humidified Incubation



Imaging &
Recovery




FIG. 5




FIG. 6

10.290" 95646860




FIG. 7A







FIG. 7B



A.



B.



C.

FIG. 8

Capillary array.




FIG. 9A




FIG. 9B

09894956.062701





FIG. 10

Automated Hit Detection & Recovery System

FIG. 11

100






FIG. 12C




FIG. 12 D